

To: Way, Steven[way.steven@epa.gov]
From: Kirstin Brown - DNR
Sent: Thur 2/13/2014 5:14:22 PM
Subject: Re: Elevations of GK and RB

Will send tomorrow. Yes I have looked at that. The Bonita fault also dips away from the r and b workings

Kirstin Brown
Sent from my iPhone

On Feb 13, 2014, at 7:38 AM, "Way, Steven" <way.steven@epa.gov> wrote:

Kirstin,

That's a great figure – thanks for providing that. Another question might come up and that is the position of the back end of R n B relative to the Bonita fault at that elevation. Have you looked at the larger structures relative to the mines and mapped those also ?

Thanks again,

Steve

Federal On-Scene Coordinator

Emergency Response Program (8EPR-ER)
US EPA Region 8
1595 Wynkoop Street
Denver, CO 80202-1129

Office: 303-312-6723

From: Brown - DNR, Kirstin [<mailto:kirstin.brown@state.co.us>]
Sent: Wednesday, February 12, 2014 2:45 PM
To: Way, Steven
Cc: Allen Sorrenson - DNR
Subject: Elevations of GK and RB

Steve,

Here is an image with elevation annotations.

I may have R&B at wrong elevation - I chose 10,955

I noticed that I am missing Level 6 of Gold King workings - it is a small level with minimal workings... The Level 6 map does not have an elevation, that is why it is missing I think.

Kirstin

--

Kirstin Brown

Colorado Division of Reclamation, Mining and Safety

691 C.R. 233, Suite A-2

Durango, CO 81301

(970) 903-7889

kirstin.brown@state.co.us